

## **FIELD INSPECTION**

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant	
Inspection Date:	Thursday, February 14, 2019	Project Contact:	Brian Clauto	
Spread: Montgomery County MP 227 St#12035+19 & 12031+56 MP 228 St#12076+95	Spread H	Weather (Wet/Dry/Rain):	Dry	
STAGE OF CONSTRUCTI	ON: (Check all that apply)			
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation	
Backfilling and Grade	e Restoration	& Stabilization	Other: Dormant	
<ul> <li>erosion and sedime</li> <li>Are all control meas</li> <li>condition in accorda applicable, manufac</li> <li>Areas of offsite sedi</li> </ul>	d and implemented in accordance with the nt control plan and stormwater managementers properly maintained in effective oper unce with good engineering practices and, sturer specifications?  ment deposition were observed?	ent plans? rating		
no impacts were ob	ed streams included: S-G36, S-G40, oserved at the time of the inspection.  Corrective Action: N/A	S-G39, and S-MM15. ECD	were in place near all the streams,	

## **Deadline:** \_N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:	Matthe Haw	_	Date:	3-1-19
mopositi dignataro			Date.	<u> </u>



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date:Thursday, February 14, 2019

 Fig. 1 Area near designated stream S-G36 has been temporarily stabilized and controls are in place.



 Fig. 2 Area near designated stream S-G40 has been temporarily stabilized and controls are in place.



 Fig. 3 Area near designated stream S-G39 has been temporarily stabilized and controls are in place.



• Fig. 4 Area near designated stream S-MM15 has been temporarily stabilized and controls are in place.

